



Note: It is the responsibility of the machine builder to make a risk assessment and make sure that the appropriate functional safety levels are achieved.

Anmärkning Remark	Konstr Design	Godk Appr	Datum Date		Blad Sheet
			20210707		
BSR11 general	Ritad Drawn	Sidor Pages	Ritn nr Drawing no		Forts Cont
			2TLC010005T0001		







Note: It is the responsibility of the machine builder to make a risk assessment and make sure that the appropriate functional safety levels are achieved.

Anmärkning Remark	Konstr Design	Godk Appr	Datum Date		Blad Sheet
			20210707		
BSR11/BSR10 as expansion relay	Ritad Drawn	Sidor Pages	Ritn nr Drawing no		Forts Cont
	ABB		2TLC010005T0004		

