


Note: It is the responsibility of the machine builder to make a risk assessment and make sure that the appropriate functional safety levels are achieved.

Anmärkning Remark	Konstr Design	Godk Appr	Datum Date		Blad Sheet
			ABB	20210707	
BSR10 general	Ritad Drawn	Sidor Pages	Ritn nr Drawing no		Forts Cont
			ABB	2TLC010004T0001	






PLe
According to
EN ISO 13849-1

Note: The stated PL is only valid if all relevant requirements according to EN ISO 13849-1/-2 are met. It is the responsibility of the machine builder to make a risk assessment and make sure that the appropriate functional safety levels are achieved.

Anmärkning Remark BSR10 as PLUTO expansion	ABB Safety Products		Konstr Design	Godk Appr	Datum Date	Blad Sheet
			ABB		20210705	
			Ritad Drawn	Sidor Pages	Ritn nr Drawing no	Forts Cont
			ABB		2TLC010004T0002	



PLe
According to
EN ISO 13849-1

Note: The stated PL is only valid if all relevant requirements according to EN ISO 13849-1/-2 are met. It is the responsibility of the machine builder to make a risk assessment and make sure that the appropriate functional safety levels are achieved.

Anmärkning Remark BSR10 with INCA1	ABB Safety Products		Konstr Design	Godk Appr	Datum Date	Blad Sheet
			ABB		20210705	
			Ritad Drawn	Sidor Pages	Ritn nr Drawing no	Forts Cont
			ABB		2TLC010004T0004	