



- A) Two signals from T1/T2
- B) One signal from T1
- C) Two OSSD signals
- D) Two signals from +24VDC
- E) One signal from +24VDC
- F) Automatic reset

Note: It is the responsibility of the machine builder to make a risk assessment and make sure that the appropriate functional safety levels are achieved.

Anmärkning Remark	SSR32 general	ABB Safety Products	Konstr Design	Godk Appr	Datum Date	Blad Sheet
			ABB		20210707	
			Ritad Drawn	Sidor Pages	Ritn nr Drawing no	Forts Cont
			ABB		2TLC010011T0001	