



Note: The stated PL is only valid if all relevant requirements according to EN ISO 13849-1/-2 are met. It is the responsibility of the machine builder to make a risk assessment and make sure that the appropriate functional safety levels are achieved.

Anmärkning Remark

SSR20M with JSTD1-A

Ass Safety Products

ABB	nGodk	Appr	20210706	RIGG	Sneet
Ritad Drawr ABB	Sidor		Ritn nr Drawing no 2TLC010010T0002	Forts	Cont